

03500.016212



**PATENT** 

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)	) : Examiner: V. Tran ) : Group Art Unit: 2115 )	
TADAAKI MAEDA	)		
oplication No.: 10/078,396	: )		• -
Filed: February 21, 2002	: )		Certificate
For: MEMORY CONTROL DEVICE HAVING LESS POWER CONSUMPTION FOR BACKUP	; ; ;		APR 1 9 2006  of Correction
U.S. Patent No.: 6,981,159	)		
Issued: December 27, 2005	;	Date: April 13, 2006	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

# REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

Patentees' undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

Michael K. O'Neill Attorney for Patentee Registration No.: 32,622

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

CA\_MAIN 112312v1

# Stable Here Only! PRINTER'S TRIM LINE

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,981,159

DATED

December 27, 2005

INVENTOR(S) :

TADAAKI MAEDA

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# **COLUMN 8**

Line 40, "taining," should read --taining--; and Line 54, "alter" should read --after--.

### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) 90920 (Form#30)

PATENT NO. 6,981,159

No. of add'l. copies @ 30¢ per page

APR 20 2006